

TILLAMOOK COUNTY

Returning to the 1/4 corner between sections 2 and 1, we ran

S. 89° 39'E. thru the center of section 1.

26+44.9

Intersect the N. & S. centerline of the section at Sta. 26+74.2, the temporary center of section. We place a concrete pedestal 12" square at top, 18" square at bottom and 36" high, set 24 inches in the ground, with a 2 1/2" brass disc on which is stamped a circle and the number 1 and, circumferentially, CEN. SEC. T. 3 N. R. 6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled CENTER SEC. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black. No live trees available for bearing trees.

53+50.5

The 1/4 corner between sections 1 and 6, previously described.

Returning to the South 1/16 corner on the line between sections 2 and 1, we ran thence,

S. 83° 25 1/2'E. between the North and South halves of the S.W. 1/4 of section 1.

13+34.4

Set 3/4"X 30" iron pin for the center of the S.W. 1/4 of section 1. Also set a 4"X 4" white guard post stenciled 1/16 SEC. COR. on 2 faces and O.S.H. PROP. COR. on 2 other faces in black.

26+68.8

The South 1/16 corner on the N. & S. centerline of the section.

From the 1/4 corner between sections 2 and 1, we ran Westerly by traverse along the highway to the 1/4 corner between sections 3 and 2, thence Southerly by traverse to the corner to sections 3-2-10-11.

At the quarter corner between sections 3 and 2, we found a 60" live fir for the N.W. bearing tree. Setting a point for the 1/4 corner from this tree, we found a rotten fir stump in proper position for the other ~~bearing~~ bearing tree. For the quarter corner, we place a concrete pedestal 12" square at top, 18" square at bottom and 36" high, set 24 inches in the ground, with a 2 1/2" brass cap on which is stamped a line with short cross mark and the numbers 3 and 2 and, circumferentially, 1/4 COR. T. 3 N. R. 6 W. W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled 1/4 SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black. We marked one new bearing tree as follows:

A 30" fir bears N. 85° E. 60.2 ft., scribed 1/4 S. B.T. (since broken off about 6 ft. above the ground.)

At the corner to sections 3-2-10-11 we found a 56" scribed fir snag and 3 rotten stumps in proper position for the other bearing trees. For the section corner we set a 2"X 48" galv. iron pipe with brass cap on which is stamped a cross and the numbers 3-2-10-11 and, circumferentially, SEC. COR. T. 3 N. R. 6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled SEC. COR. on 2 faces in black, and marked 4 new bearing trees, as follows:

- An 8" fir bears N. 40° E. 31.6 ft., scribed T. 3 N. R. 6 W. S.2 B.T.
- An 8" fir bears N. 65° W. 20.1 ft. scribed T. 3 N. R. 6 W. S.3 B.T.
- A 10" fir bears S. 30° W. 29.1 ft., scribed T. 3 N. R. 6 W. S.4 B.T.
- A 12" fir bears S. 60° E. 37.0 ft., scribed T. 3 N. R. 6 W. S.11 B.T.