

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter section corner common to Sections 7 and 12 T1S  
R 6 & 7, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a :

18" Hem. bears N49 $\frac{1}{2}$ °E 37 lks; now 22" stub 12' high,  
part of scribe S and BT visible, rest burnt off.

7" Vinemaple bears S24°W 3 lks.; now missing, possible roots at  
point.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S7 S12 1954 RE2311,"  
34" inches inground, in mound of stone, and from which a:

60" Fir stump bears S75°W 11.8 ft.; scribed 1/4 S12 BT RE2311.

56" Fir snag bears N89°E 73.0 ft.; scribed 1/4 S7 BT.

Oregon State Board of Forestry metal location poster on 56"  
snag BT. Set 4" x 4" x 84 " white Cedar post 2 ft. SW  
of pipe.

Dated December 31, 1954

Restored by Richard Morris under my direction  
Richard Morris, Engr. Aide.



Present and witnessed by Lloyd Geraths  
Forrest Logan