

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 27, 28, 33 and 34,  
T3N, R8W, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing from which a:

- 12" Hem. bears N70°E 13 lks.; now 11" uproot out of place, roots in place, scribes BT visible, rest missing.
- 24" Hem. bears S63E 62 lks.; now 36" snag, bottom lower face visible, rest burnt out.
- 18" Hem. bears S60°W 29 lks.; now 23" snag, scribes T3N R8W S33 BT visible.
- 10" Hem. bears N78°W 62 lks.; now missing, trace of roots remaining.

RESTORED

Set 1½" x 42" galvanized iron pipe with 3" bronze cap ~~cap~~ marked "OREGON STATE BOARD OF FORESTRY T3N R8W S28 S27 S33 S34 1954 RE2311," 38 inches in ground, in mound of stone, and from which a:

- 54" Fir stump bears N22°E 6.2 ft.; scribed T3N R8W S27 BT RE2311.
- 47" Fir stump bears N15°W 21.9 ft.; scribed T3N R8W S28 BT.
- 48" Fir snag bears S34E 98.7 ft.; scribed T3N R8W S34 BT.
- 52" Fir stump bears S46W 63.6 ft.; scribed T3N R8W S33 BT.

Oregon State Board of Forestry metal location poster on 54" Fir stump BT. Old poster original 23" Hem. snag BT. Set 4" x 4" x 84" White Cedar post 1 ft. SE of pipe.

Dated December 31, 1954.

Restored by Richard Morris under my direction  
Richard Morris, Engr. Aide



Present and witnessed by Forrest Logan  
Claude Weikel  
Lloyd Geraths