

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 7 and 8, T 3N  
R 6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, found rotted point in place, from which a:

- 12" Hemlock bears N54°E 32½ lks.; now 19" stump, scribes BT visible, upper face burnt out.
- 60" (each) Double Fir bears S23½°E 49 lks.; now 60" (each) double stumps, scribes T3N R6W S8 visible on charred face, lower face unexposed.
- 36" Hemlock bears S45°W 10 lks.; now 38" stump, face burnt out no scribes visible, scribes BM 2500x2 visible on root crown.
- 30" Hemlock bears N52°W 64 lks.; now 37" stump, face burnt out, no scribes remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S6 S5 S7 S8 1955 RE 2311," 33 inches in ground, in mound of stone, and from which a:

- 31" Fir stump bears N86½°E 48.4 ft.; scribed T3N R6W S5 BT RE 2311.
- 52" Fir stump bears N18½°W 45.0 ft.; scribed T3N R6W S6 BT
- 38" Fir stump bears S53°W 90.7 ft.; scribed T3N R6W S7 BT
- 55" Fir stump bears S47°E 105.0 ft.; scribed T3N R6W S8 BT

Set 4"x4"x65" white Cedar post 2' NE of pipe.  
Oregon State Board of Forestry metal location poster on 31" Fir stump BT.  
Oregon State Board of Forestry metal location poster on original 60" (each) double Fir stump.  
Oregon State Board of Forestry metal location poster on 4"x4"x65" white Cedar post on N edge Rd. approx. 200' N.

Dated February 28, 1955.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Forrest Logan  
Claude Weikel