

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 29 and 30,  
T. 2S., R. 6W., W.M., Tillamook and Yamhill Counties,  
Oregon.

ORIGINAL

Post, now missing, from which a:

- 10" Hemlock bears S45°E 60 lks.; now 10" 4 ft. high stub, original axe work visible on lower face.
- 20" Hemlock bears N65°W 28 lks.; now 24" uproot, part of scribes  $\frac{1}{4}$  S remaining.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$  S30 S29 1955 RE 2311," 31 inches in ground, in mound of stone, and from which a:

- 5" Fir bears N32°E 105.2 ft.; scribed  $\frac{1}{4}$  S 29 BT.
- 5" double Fir (each) bears S74°W 154.5 ft.; scribed  $\frac{1}{4}$  S30 BT RE 2311.

Set 3"x3"x72" white painted Cedar post 2.5 ft. NE of pipe.

Oregon State Board of Forestry metal location poster on 32" Fir stub S48°E 41.6 ft.

Dated May 17, 1955.

Restored by Arnold G. Gibson under my direction.  
Arnold G. Gibson, Assistant Engineer



Present and Witnessed by Richard Morris  
Robert Sturm  
Lloyd Geraths