

CHAINS

Restored Corner for Oregon State Board of Forestry

One quarter corner common to Sections 17 and 18,
T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Stake, now missing, from which a:

24" Hemlock bears N54°15'E 42 lks.; now 28" snag, edges of
burnt out original face remaining.

36" Fir bears N71°0'W 23½ lks.; now 40" stump, scribes BT
remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY ¼ S17 S18 1955 RE2311," 32
inches in ground, in mound of stone, and from which a:

7" Fir bears S5°0'W 3.2 ft.; scribed ¼ S18 BT RE2311.

6" Hemlock bears S23½°E 18.7 ft.; scribed ¼ S17 BT.

Set 4"x3"x72" white painted Cedar post 2 ft. NW of pipe.

Oregon State Board of Forestry metal location poster on 7" Fir BT.

Dated June 6, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Lloyd Geraths
Robert Sturm
Forrest Logan