

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17,
T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

56" Fir, now 50" stump, 4 notches on S side and 4 on E, scribes
S16 visible on SE side, R6W on edges burnt NE face, axe marks
remaining on NW & SW sides, from which a:

- 40" Hemlock bears N76 $\frac{1}{2}$ °E 25 lks.; now 40" rotted stub 8 ft.
high, bottom original face remaining.
- 18" Hemlock bears S6°E 29 lks. ; now 24" 2 ft. high root stub.
- 30" Fir bears S24°W 31 lks.; now 32" uproot, position of face
covered with dirt.
- 16" Hemlock bears N40°W 52 lks.; now 12" 1 ft. high stub.

RESTORED


Set 4"x3"x72" white painted Cedar post on SE edge Fir stump corner,
from which a:

- 8" Fir bears N40°W 16.7 ft.; scribed T3N R6W S8 BT.
- 11" Fir bears S36°E 26.0 ft.; scribed T3N R6W S16 BT.
- 7" Fir bears S65°W 31.1 ft.; scribed T3N R6W S17 BT.
- 7" Fir bears N4 $\frac{1}{2}$ °E 32.7 ft.; scribed T3N R6W S9 BT.

Oregon State Board of Forestry metal location poster on 8" Fir BT.
Also poster on 3"x4"x72" white painted Cedar post approximately
1520 ft. East on West edge road.

Dated June 9, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide.



Present and witnessed by Robert Sturm.