

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 6 and 7 (West side)  
Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

50" Cedar bears N51°E 14 lks.; now 72" snag scribes S R8W remaining on charred face.

5" Vine Maple bears S34°E 18 lks.; now missing, vine Maple clumps found in vicinity.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R9W R8W S12 S6 S7 1955 RE 2311," 34 inches in ground, and from which a:

15" Fir bears S67°E 4.7 ft.; scribed T1S R8W S7 BT RE 2311.

10" Hemlock bears N12°E 17.9 ft.; scribed T1S R8W S6 BT.

Set 3"x4"x54" white painted Cedar post 1 ft. W. of pipe.  
Oregon State Board of Forestry metal location poster on 15" Fir BT.

Also poster on N side original 28" fir line tree 25 lks. South of ridge top and 672.6 ft. North of corner.

Dated June 22, 1955

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths  
Forrest Logan  
Robert Sturm