

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 7, 8, 17 and 18,
T3N, R6W, W.M., Tillamook County, Oregon

ORIGINAL

Mark stone with X in face 45° slope (found) from which a:

- 16" Hemlock bears N50°20'E 50 lks.; now 17" stump, bottom original face remaining.
- 36" Hemlock bears S30°30'E 129 lks.; now 36" stump, original axe work and portion of scribe remaining.
- 14" Hemlock bears S32°W 18 lks.; roots remaining in place.
- 6" Hemlock bears N41°45'W 115 lks.; now 12" stump, scribes T3N R6W S7 BT visible.
- 15' Waterfall bears S35°W 40 lks.; in place.

RESTORED

Chiseled X deeper into 45° rock face and nailed OSBF metal location poster over X, from which a:

- 6" Fir bears N17°W 138.8 ft.; scribed T3N R6W S7 BT and located 40 ft. N of road.
- 6" Fir bears S51°W 35.7 ft.; scribed T3N R6W S18 BT and located 5 ft. W of edge of 15 ft. waterfall.
- 7" Fir bears S13°E 28.5 ft.; scribed T3N R6W S17 BT RE2311.
- 10" Noble Fir bears N4°E 74.1 ft.; scribed T3N R6W S8 BT.

Set 4"x4"x72" white painted Cedar post in mound of stone 4 ft. NW of corner.

Oregon State Board of Forestry metal location poster on 6" Fir BT N17°W.

Also poster on 4"x3"x72" white painted Cedar post on W edge road 107.4 ft. W of corner.

Dated June 9, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Lloyd Geraths
Forrest Logan
Robert Sturm