

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 8 and 17,  
T3N, R6W, W.M., Tillamook County, Oregon

ORIGINAL

Stake, now missing, from which a:

24" Hemlock bears S49°E 41 lks.; now 26" uproot, downhill out  
of place; original axe marks visible.

60" Fir bears N4°E 53 lks.; now 47" stump, scribes  $\frac{1}{4}$ " S BT visible.

RESTORED

Set  $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$ " S8 S17 1955 RE2311," 32  
inches in ground, in small mound of stone, and from which a:


8" Fir bears N57 $\frac{1}{2}$ °E 29.2 ft.; scribed  $\frac{1}{4}$ " S8 BT RE2311.

7" Fir bears S82°E 48.5 ft.; scribed  $\frac{1}{4}$ " S17 BT.

Set 3"x3"x72" white painted Cedar post 1.5 ft. NE of pipe.  
Oregon State Board of Forestry metal location poster on 8" Fir BT.

Dated June 9, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Engineering Aide



Present and witnessed by Lloyd Geraths  
Forrest Logan  
Robert Sturm