

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 26,27,34 and 35,
T. 1S, R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18"x12"x10", now missing, from which a:

- 24" Spruce bears N61°E 100 lks.; now 60" snag, scribes R8W visible, rest burnt out.
- 6" Barberry bears S88°E 140 lks.; now missing.
- 10" Alder bears S53°W 41 lks.; now 25" uproot, root hole in place, rotted off face with axe marks but no scribes remaining.
- 8" Alder bears N28°W 28 lks.; now 23" still green, rotted out face with axe marks around edge, no scribes remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R8W S27 S26 S34 S35 1955 RE 2311," 33 inches in ground, in mound of stone, and from which a:


- 18" Alder bears N83°E 38.0 ft.; scribed T1S R8W S26 BT.
- 25" Alder bears N86°W 21.0 ft.; scribed T1S R8W S27 BT RE 2311
- 11" Alder bears S47½°E 59.7 ft.; bark scribed T1S R8W S35 BT.
- 5" Spruce bears S15°W 56.4 ft.; scribed T1S R8W S34 BT.

Oregon State Board of Forestry metal location poster on 18" Alder BT.

Set 4"x4"x60" white Cedar post 1 ft. NW of pipe.

Dated April 11, 1955.

Restored by Richard A. Morris under my direction.
R. A. Morris, Engr. Aide



Present and witnessed by Claude Weikel
Forrest Logan
Lloyd Geraths

C
Book I
233

Book I