

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 1 and 12,
T. 2 N., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone 18" x 12" x 7", missing, from which a:

16" Alder bears S55°E 39 lks.; now 19" x 15 ft. high
stub, scribes $\frac{1}{4}$ remaining.

7" Maple bears North 57 lks.; now missing.

RESTORED

Var. $21\frac{1}{2}^\circ$

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S1 S12 1955
RE 2311," 33 inches in ground, in mound of stone,
and from which a:

6" Cedar bears N82°W 67.5 ft.; scribed $\frac{1}{4}$ S1 BT.

37" Hemlock bears S31°W 86.6 ft.; scribed $\frac{1}{4}$ S12 BT RE 2311.

Set 4" x 4" x 72" white painted cedar post 2 ft. SE of
pipe.

Oregon State Board of Forestry metal location poster on
7" Alder S6°E 17.5 ft.

Also poster on 4" x 4" x 60" white painted Cedar post
390 ft. East on East bank log road.

Dated September 1, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Forest Logan
Robert Sturm