

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 24 (East side)
T3N, R7W, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 12" Hemlock bears N46°W 7 lks.; roots and root hole in place.
- 36" Fir bears S72°E 20 lks.; now 28" snag, scribes 1/4 remaining.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S24 1955 RE 2311," 33
inches in ground, and from which a:

24" Fir snag bears S38°W 36.1 ft.; scribed 1/4 S24 BT RE2311.

Set 4" x 4" x 60" white painted Cedar post 1.5 ft. NE of pipe.
Oregon State Board of Forestry metal location poster on 24" Fir
snag BT.

Dated September 16, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Engr. Aide



Present and witnessed by Forest Logan
Lloyd Geraths
Robert Sturm