

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to Sections 20 and 21, T. 1S.,
R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

40 chains N., post, now missing from which a:

10" Hemlock bears S32 $\frac{1}{2}$ °E 63 lks.; now 6" uprooted stub,
roots in place, scribes $\frac{1}{4}$ " S BT visible.

4" Barberry bears N89 $\frac{1}{2}$ °W 13 lks.; now missing.

41 chains N., creek 5 lks. wide course SE and about 5 chains
below 75' waterfall (now in place)

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ " S20 S21 1955
RE 2311," 30 inches in ground, in mound of stone, and
from which a:

48" Fir snag bears S60°E 43.8 ft.; scribed $\frac{1}{4}$ " S 21 BT
RE 2311.

65" Fir snag bears S17°W 32.2 ft.; scribed $\frac{1}{4}$ " S20 BT.

Set 4"x4"x72" white painted Cedar post 3' SW of pipe.
Oregon State Board of Forestry metal location poster on
48" Fir snag BT.

Also poster on 4"x4"x72" white painted Cedar post approx.
200' N6°W on N. edge logging road.

Dated September 20, 1955

Restored by Richard A. Morris under my direction.
Richard A. Morris, C. E. I



Present and witnessed by Lloyd Geraths
Forrest Logan
Robert sturm