

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to Sections 24 and 25, T. 3N.,
R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20" x 8" x 5" found in place with $\frac{1}{4}$ on N. side,
from which a:

- 36" Fir bears S10°E 36 lks.; now 47" stump, scribes BT visible in bark face, upper face cut off when logged.
- 9" Hemlock bears N61°E 43 lks.; now 13" uproot, roots and roothole in place, scribes BT visible, upper face burnt out.

RESTORED

Var. 21 $\frac{1}{2}$ °E

Erected mound of stone around original $\frac{1}{4}$ stone, from which a:

- 5" Noble Fir bears South 57.5 ft.; scribed $\frac{1}{4}$ S25 BT RE 2311.
- 22" Fir stump bears N39°E 33.4 ft.; scribed $\frac{1}{4}$ S24 BT.

Set 4"x4"x72" white painted Cedar post 1.5' NW of $\frac{1}{4}$ stone.
Oregon State Board of Forestry metal location poster on 5" Noble Fir BT.

Also poster on 4"x4"x60" white Cedar post approx. 860' W.
on W edge logging road.

Dated September 20, 1955

Restored by Richard A. Morris under my direction.
Richard A. Morris, C.E.I



Present and Witnessed by Forrest Logan
Lloyd Geraths
Robert Sturm