

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

) Section corner common to Sections 29, 30, 31 and 32,
T. 1N, R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now rotted, found paint in place)) from which a:

5" Hemlock bears S73°E 23 lks.; now 3" uproot in place,
scribes S32 BT visible.

4" Hemlock bears N34°E 27 lks.; now 7" scribes S29 visible,
rest unexposed.

12" Hemlock bears N49°W 23 lks.; now 22", face unexposed.

48" Fir bears S27°W 6 lks.; now 49", face unexposed.

RESTORED

Var. 21½°


Set 1½" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY T1N R6W S29
S30 S31 S32 1956 RS 359," 26 inches in ground, and
from which a:

36" Fir bears S20°E 13.0 ft.; scribed T1N R6W S32 BT
RS 359.

Oregon State Board of Forestry metal location posters on
Original 12" Hemlock BT and 36" Fir BT.

Dated June 15, 1956.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm
Lloyd Geraths
R. Schildknecht