

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 31 and 32 (Base Line)  
T. 1N, R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a: )

- 40" Fir bears N50°W 8 lks.; now 51", face unexposed.
- 8" Hemlock bears N27°E 54 lks.; now 27", scribes R6 S32 visible, rest unexposed.
- 36" Fir bears S30°E 26 lks.; now 36" snag, scribes BT remaining.
- 8" Hemlock bears S58°W 45 lks. now 23", face unexposed.
- Bench mark on 22" Hemlock bears N2°W 11.1 ft.; scribes BM 3066.55 visible.

RESTORED

Var. 21½°



Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY BL T1N R6W S31 S32 1956 RS 359," 34 inches in ground, and in small mound of stone.

Set 4"x4" x60" white painted Cedar post 1 ft. SE of pipe.

Oregon State Board of Forestry metal location poster on 8" Hemlock N84°E 20.2 ft.

Dated June 15, 1956

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm  
Lloyd Geraths

Book I