

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 19, 20, 29 and 30 T. 3S.,
R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

48" Fir bears S.20°E. 77 lks.; now 45" snag, scribes and
face rotted off.

48" Fir bears N.62°W. 47 lks.; now 47" uproot, scribes
and face rotted off.

36" Fir bears S.37°W. 108 lks.; now 30" x 5' high stub,
scribes and face rotted off.

NOTE: Retracement by O.S.B.F. of a survey made by U. G.
Jackson, C. S., in 1913, from the 1/4 and N. 1/16
of Sec. 29 and 30 puts the section corner within 3 ft.
of this point.

RESTORED

Var 21-1/2°

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T3S R9W S19 S20 S29 S30
1956 REL697," 33 inches in ground, in small mound of
stone, and from which a:

26" Hemlock bears N.65°E. 12.1 ft.; scribed CS T3S R9W
S20 BT REL697.

9" Hemlock bears S.22 1/2°E. 14.4 ft.; scribed CS T3S R9W
S29 BT.


17" Alder bears N.41°W. 59.5 ft.; scribed CS T3S R9W S19
BT (in bark)

14" Fir bears S.64°W. 100.4 ft.; scribed CS T3S R9W S30
BT.

Set 4" x 4" x 72" white painted cedar post 2' S.W. of pipe.
Oregon State Board of Forestry metal location poster on 26"
Hemlock BT.

Dated August 8, 1956

Restored by Richard Morris under my direction
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm