

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 24 and 25, Township 1S,
R. 7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

12" Hemlock bears N.87°W. 85 lks.; now 24" stub 10' high,
scribes 1/4 S visible, rest unexposed.

Hemlock bears S.49°W. 58 lks.; now missing.

RESTORED

Var. 21½° E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S24 S25 1956 RS359,"
33 inches in ground, in mound of stone, and from which a:

58" Fir snag bears S.40°E. 96.6 ft.; scribed 1/4 S25 BT
RS359.


66" Fir snag bears N.45°W. 123.3 ft.; scribed 1/4 S24 BT.

Oregon State Board of Forestry metal location poster on 58"
Fir Snag BT.

Set 4" x 4" x 72" white painted Cedar post 1.5' SW of pipe.

Dated May 14, 1956

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm