

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

Center West one-sixteenth corner in Section 30,
T3S, R9W, W.M., Tillamook County, Oregon.

ESTABLISHED 1887 (see county records)

(no evidence of established corner found)

REESTABLISHED

Var. $21\frac{1}{2}^{\circ}$ E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY W 1/16 C - C
S30 1957 RS 359," 33 inches in ground, in mound of
stone, and from which a:

10" Fir bears $N46^{\circ}$ E 56.0 ft.; scribed CW 1/16 S30 BT
RS 359.

12" Spruce bears $S14\frac{1}{2}^{\circ}$ W 48.1 ft.; scribed CW 1/16 S30 BT.

Oregon State Board of Forestry metal location poster on
12" Spruce BT.

Set 4"x4"x60" white painted Cedar post 2 ft. NE of pipe.

One quarter corner common to Sections 25 and 30,
T3S, Rges. 9 and 10W, W.M., Tillamook County, Oregon.

ORIGINAL

(no evidence of original corner found)

RESTORED 1887 (see county records)

(no evidence of restored corner found)

REESTABLISHED

Var. $21\frac{1}{2}^{\circ}$ E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S25 S30
1957 RS 359," 35 inches in ground, and from which a:

22" Hemlock bears $S77^{\circ}$ W 7.6 ft.; scribed $\frac{1}{4}$ S25 BT RS 359.

16" Fir bears $N32^{\circ}$ E 49.9 ft.; scribed $\frac{1}{4}$ S30 BT.


Oregon State Board of Forestry metal location poster on
22" Hemlock BT.

Set 4"x4"x60" white painted Cedar post 1.0 feet NW of pipe.

Dated February 21, 1957.

Reestablished by Richard Morris under my direction.
Richard Morris, Transitman

Present and witnessed by Lloyd Geraths & Robert Sturm



Book I