

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner to Sections 31 and 32 (base line)
T. 1N, R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Hemlock bears N52½°E 61 lks.; now 35" snag, scribes R 8W T N 32 BT visible.
- 32" Hemlock bears N20½°W 35 lks.; now 36" snag, scribes R 8W T N S 31 BT visible.
- 12" Hemlock bears S73½°E 44 lks.; now 16 x 10 ft. high stub, scribes R8W T1S S5 visible (reported destroyed by T1S R8W survey).
- 32" Hemlock bears S22°W 38 lks.; now 26" snag, scribes R8W BT visible, rest burnt off (reported destroyed by T1S R8W survey).

RESTORED

Var. 21½°


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R8W BL S31 S32 1956 RS. 359," 33 inches in ground, in mound of stone, and from which a:

- 7" Alder bears N30°E 49.1 ft.; scribed T1N R8W S32 BT (bark scribed)
- 56" Fir snag bears N87°W 12.2 ft.; scribed T1N R8W S31 BT RS 359.

Set 4"x3"x60" white painted Cedar post 1.5 ft. SW of pipe. Oregon State Board of Forestry metal location poster on 10" Alder N28°W 11.3".

Dated November 28, 1956.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm