

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 26, 27, 34 and 35, T. 1N., R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

16" x 8" x 6" basalt stone (found possible corner stone 16" x 12" x 8", no notches visible, laying on top of ground.)
from which a:

14" hemlock bears N.49°E 64 lks.; now 36" snag, scribes R9W S2 visible on partially rotted face.

RESTORED

Var. 21½° E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R9W S27, S26 S34 S35 1957 RS401," 33 inches in ground, in mound of stone, and from which a: / (between roots of an Alder)

9" Spruce bears S46½°E 40.8 ft.; scribed T1N R9W S35 BT.

7" Hemlock bears N89½°W 66.8 ft.; scribed T1N R9W S27 BT.

11" Spruce bears N11½°E 1.2 ft.; scribed T1N R9W S26 BT

34" Hemlock bears S84°W 43.5 ft.; scribed T1N R9W S34 BT RS401

Oregon State Board of Forestry metal location poster on 34" Hemlock BT.


Set possible original corner stone on E. side of pipe.
Set 4" x 4" x 60" white painted cedar post 2.2' SW

Dated August 5, 1957

Restored by _____



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell