

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11
T. 1S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 15" x 12" x 12" (now missing) from which a:

- 12" Hemlock bears S9 $\frac{1}{2}$ °E 25 lks.; now 26" stub, 15' high, scribes S R9 11 visible, rest unexposed.
- 12" Hemlock bears N34°E 60 lks.; now missing, point falls in slide.
- 20" Hemlock bears N59 $\frac{1}{2}$ °W 79 lks.; now 30" stump, scribes visible on partially exposed face.
- 12" Hemlock bears S70 $\frac{1}{2}$ °W 83 lks.; now 26" Spruce stump, scribe S visible on partially exposed face, distance now 49.3'.

RESTORED

Var. 21 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R9W S3 S2 S10 S11 1957 RS401," 33 inches in ground, in mound of stone, and from which a:

- 11" Alder bears S55°E 28.7 ft.; scribed in bark, T1S R9W S11 BT RS401.
- 6" Alder bears S67°W 16.6 ft.; scribed in bark, T1S R9W S10 BT.
- 5" Alder bears N46°E 13.0 ft.; scribed in bark, T1S R9W S2 BT.
- 30" Hemlock bears N32°W 103.7 ft.; scribed T1S R9W S3 BT.


Oregon State Board of Forestry metal location poster on 6" Alder BT. Set 4" x 4" x 60" white painted Cedar post 1.0' SE of pipe.

Dated October 25, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell