

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 4, 5, 8 and 9
T. 1S, R. 6W, W.M., Washington and Tillamook Counties, Oregon.

ORIGINAL

Stone 10" x 10" x 7" (now missing, point falls in slide area)
from which a:

- 9" Hemlock bears N49°W 51 lks.; now missing, point falls in slide area.
- 24" Fir bears N22½°E 104 lks.; now 42" stub 15' high, faces unexposed, distance now 61.1 ft.
- 30" Fir bears S36½°E 79 lks.; now 31" stump, scribes T1S R6W S9 visible, lower face burnt out.
- 10" Hemlock bears S62½°W 21 lks.; now missing, point falls in slide area.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R6W S5 S4 S8 S9 1957 RS401," 33 inches in ground, in mound of stone, and from which a:

- 47" Fir stump bears N37°W 33.2 ft.; scribed T1S R6W S5 BT RS401.
- 48" Fir stump bears S1°W 20.8 ft.; scribed T1S R6W S8 BT.
- 53" Fir stump bears S18°E 52.8 ft.; scribed T1S R6W S9 BT.


Oregon State Board of Forestry metal location poster on 53" Fir stump BT. Set 4" x 4" x 72" white painted Cedar post 1.4' NE of pipe.

Dated October 25, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell

Book I