CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Section 1 (East side) T. 1S, R. 8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 8" x 8" (now 16" x 7" x 7", marked 1/4 on W. side) from which a:

6" Maple bears N31W 10 1ks.; now 8" uproot, roots in place, with old axe work and burnt out face.

6" Maple bears N52E 20 lks.; now missing, vine maple clumps in vicinity.

RESTORED by A. V. Benedict Feb. 12, 1942

Set 4.5' piece 12" iron pipe, 3.5' in ground, (now in place on E edge of above original stone)

Marked no new BTs.

RESTORED

Var. $2l\frac{1}{2}E$

Erected mound of stone around original stone and above pipe, from which a

Alder bears S52W 30.0 ft.; scribed in bark, 1/4 S1 BT RS 401.

7" Alder bears N55W 35.8 ft.; scribed in bark 1/4 S1 BT.

Oregon State Board of Forestry metal location poster on 7" Alder BT. Set 4" x 4" x 72" white painted Cedar post 2.0' N.E. of corner stone.

Dated March 20, 1958

REGISTERED OREGON LAND SURVEYOR

> MAY 10, 1857 Richard A. Morris 401

Present and witnessed by Robert Sturm
Harold Russell

Book I (

4 3 6

118