

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY
 Section corner common to Sections 15 and 22 (East side) T. 2S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 80" Hemlock bears N30W 68 lks.; now 80" snag, scribes R9W visible, rest rotted off.
- 12" Hemlock bears S51E 37 lks.; position now covered by logs and debris.
- 6" Hemlock bears N38E 32 lks.; now missing.
- 40" Hemlock bears S12W 33 lks.; position now covered by logs & debris.

RESTORED by W. E. Anderson June 1925

Set spruce limb (now in place scribes CCCS 15 23 16 visible)
 Set no new BTs.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S15 S14 S22 1958 RS 401," 33 inches in ground, with above spruce limb on N. edge of pipe,

- 46" Hemlock bears S62W 70.4 ft.; scribed T2S R9W S22 BT RS401.
- 38" Hemlock bears N12½W 73.7 ft.; scribed T2S R9W S15 BT.

Oregon State Board of Forestry metal location poster on 31" Hemlock, S14W 7.2 ft.

Set 4" x 4" x 72" white painted Cedar post 1.5' NE of pipe.

Dated April 4, 1958.

Restored by



Present and witnessed by Robert Sturm
 Harold Russell