

County Surveyor's Record, Tillamook County Oregon

Correction Report

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 25 and 30, T. 3S,
R. 9 & 10 W, W.M., Tillamook County, Oregon

ORIGINAL

Stone, 6" x 5" x 5", with mound of stone around (no evidence of original
corner found)

RESTORED by Hays July 1887

Post in creek (now missing) from which a:

- 10" Hemlock bears N58W 24 lks.; now 28", scribe S visible on partly
exposed face.
- 24" Hemlock S64E 70 lks. now 24" stub 15' high, no face or scribes
visible.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S25 S30 1958 RS359," 24 inches in ground, and from
which a:

- 20" Hemlock bears S45E 27.6 ft.; scribed 1/4 S30 BT.
- Original 28" Hemlock bears N58W 15.8 ft.; scribed BT RS359.

Oregon State Board of Forestry metal location poster on 20" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 1' NE of pipe.

Dated January 8, 1958

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Harold Russell
Lloyd Geraths