

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 4 and 9,
T. 3S, R. 8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone in gulch course S. (stone missing, gulch in place) from which a:

- 18" Maple bears N39W 100 lks.; now 36", face rotted out.
- 16" Maple bears S57E 75 lks.; now 56", face rotted out.

34" Fir line tree bears West 4.08 chs.; now 84", 3 notches on E & W sides (now 217.7' S80W).

RESTORED

Var. 21½E

Chiselled 1/4 in sandstone outcrop and drove galvanized nail in rock at corner point from which a:

- 24" Fir bears N57E 112.7 ft.; scribed 1/4 S4 BT RS401.
- 6" Cedar bears S60E 16.9 ft.; scribed 1/4 S9 BT.
- Original Maple bears N39W 66.0 ft.; scribed BT.
- Original Maple bears S57E 49.5 ft.; scribed BT.


Oregon State Board of Forestry metal location poster on 6" Cedar B.T.
Set 4" x 4" x 60" white painted Cedar post 1.3' N. in mound of stone.

Dated November 26, 1958

Restored by



Richard A. Morris



Present and witnessed by R. Schulson
H. Russell
R. Cop

Book I

350

350