

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner for Section 30 (West side),
T2S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 10" x 4" basalt stone (found downhill out of place marked 1/4)
from which a:

6" Spruce bears N60E 11 lks.; now 19" Hemlock, scribes BT Visible,
rest unexposed.

7" Spruce bears S62W 31 lks.; now 15" Hemlock snag, scribe S exposed,
rest covered.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY 1/4 S30 1959 RS401", 24 inches in ground,
at the point for corner, with original stone on East edge, in mound
of stone, and from which a:

19" Hemlock bears N82E 13.0 ft.; scribed 1/4 S30 BT RS401.

Oregon State Board of Forestry metal location poster on 19" Hemlock B.T.

Set 4" x 4" x 56" white painted Cedar post 1.0 S.E. of pipe.


Rock bluff 10' high, 25' long bears S.E. 24' from corner point.

Dated June 3, 1959.

Restored by



Richard A. Morris



Present and witnessed by H. Russell
E. Hunt