

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

RESTORED October 26, 1896 by County Surveyor's Office.

Post (now missing) from which a:

- 10" Alder bears N34 $\frac{1}{2}$ W 25 lks.; now 3' high rotten stub, face & scribes rotted away.
- 30" Hemlock bears S68W 55 lks.; now 40" snag, scribes S14 T1N R visible, rest rotted off.
- 8" Alder bears East 38 lks.; now missing.

RESTORED

Var. 21 $\frac{1}{2}$ E


Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R10W S11 S12 S14 S13 1959 RS401", 34 inches in ground, in small mound of stone, and from which a:

- 36" Hemlock bears S79W 60.8 ft.; scribed T1N R10W S14 BT RS401.
- 23" Hemlock bears N72W 60.9 ft.; scribed T1N R10W S11 BT.
- 24" Spruce bears N18E 86.5 ft.; scribed T1N R10W S12 BT.

Oregon State Board of Forestry metal location poster on 24" Spruce BT.  
Set 4" x 4" x 54" white painted Cedar post 1.0' N.W. of corner pipe.

Dated August 4, 1959

Restored by Harold Russell under my direction.  
Harold Russell, Eng. Tech. I



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401

Present and witnessed by G. Nylund  
D. Jones