

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 11 and 12,
T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 30" Hemlock bears S25W 12 lks.; now just roots remaining in place.
- 8" Hemlock bears N4E 18 lks.; now missing.

RESTORATION November 1, 1890

- 16" Hemlock bears S16W 72 lks.; now missing.
- 14" Hemlock bears N84W 123 lks.; now 39", scribes 1/4 S BT visible.

RESTORATION by County Surveyor

Stone 8" x 8" x 12" (now in place mkd. X on top) from which a:

- 10" Alder bears S63W 11.2 ft.; bark scribes CS 1/4 S BT visible.
- 11" Alder bears N18E 13.2 ft.; bark scribes CS 1/4 S BT visible.

RESTORED

Var. 21 1/2 E

Set 4" x 4" x 52" white painted Cedar post 1.0' S. W. of above stone
from which a:

- 6" Fir bears N40E 21.3 ft.; scribed 1/4 S12 BT RS401.
- Orig 14" Hemlock bears N84W 81.2 ft.; scribed BT (below old face).

Oregon State Board of Forestry metal location poster on 6" Fir BT.

Dated August 19, 1960

Restored by Harold J. Russell under my direction.
Harold Russell, Transitman

Present and witnessed by G. E. Nylund

