

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 10 and 11, T2S,
R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S10 S11 1960 RS401", 34 inches in ground, and
from which a:

- 38" Hemlock bears S25W 28.6 ft.; scribed 1/4 S10 BT RS401.
- 27" Hemlock bears N38 1/2 E 13.0 ft.; scribed 1/4 S11 BT.

Oregon State Board of Forestry metal location poster on 27" Hemlock BT.
Set 4" x 4" x 52" white painted Cedar post 1.5' N.W. of pipe.

One Quarter corner common to Sections 2 and 11,
T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S2 S11 1960 RS401", 32 inches in ground, and from
which a:

- 25" Fir bears N79W 47.0 ft.; scribed 1/4 S2 BT.
- 37" double Fir bears S36W 50.0 ft.; scribed 1/4 S11 BT RS401.
- 6" Creek course N60E, bears South 10 ft.
- 6" Creek course N60E, bears East 15 ft.
- Ravine course S70E, bears West 13.0 ft.


Oregon State Board of Forestry metal location poster on 24" Alder S38E
14.3'.

Set 4" x 4" x 52" white painted Cedar post 1.0' S.E. of pipe.

Dated August 19, 1960

REESTABLISHED by

Present and witnessed by H. Russell
R. Cop
G. Nylund
J. Sehorn



Richard A. Morris

