

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 15 and 16,
T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

9" Hemlock for 1/4 Sec. cor. (now just roots remaining, found 3/4" x 18" iron rod driven in ground alongside) from which a:

70" Fir bears S31E 30 lks.; now 70" snag, no face or scribes visible.

22" Hemlock bears S13 1/2 W 17 lks.; now just rotten roots remaining.

Summit ridge, SW & NE, bears South 100 lks.; now in place.

75" Fir line tree bears South 383 lks.; now 70" snag in place, 2 notches on S. side and 1 notch remaining on N. side, now bears S1°05'25"W 242.5'.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S16 S15 1960 RS401", 33 inches in ground, and from which a:

17" Hemlock bears N76E 12.6 ft.; scribed 1/4 S15 BT.


13" Fir bears S48 1/2 W 10.8 ft.; scribed 1/4 S16 BT RS401.

Oregon State Board of Forestry metal location poster on 13" Fir BT.

Set 4" x 4" x 54" white painted Cedar post 1.0' S.W. of pipe.

Dated May 5, 1960

Restored by



Richard A. Morris
MAY 10, 1960
Richard A. Morris
401

Present and witnessed by R. Cop
G. Nylund