

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 15, 16, 21 and 22, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 24" Hemlock bears N43 $\frac{1}{2}$ E 22 lks.; now 31" stump with scribing visible.
- 6" Hemlock bears S44 $\frac{1}{2}$ E 17 lks.; now missing.
- 18" Hemlock bears S53W 15 lks.; now 26" stub 12' high with scribing visible.
- 17" Hemlock bears N71W 56 lks.; now 10" stub 6' high, scribes T2 visible, rest burnt out.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S16 S15 S21 S22 1960 RS401", 34 inches in ground, in mound of stone, and from which a:

- 6" Fir bears S67W 15.8 ft.; scribed T3N R9W S21 BT RS401.
- 10" Fir bears N66E 56.0 ft.; scribed T3N R9W S15 BT.
- 8" Alder bears S81E 52.5 ft.; scribed in bark, T3N R9W S22 BT.
- 8" Fir bears N35W 49.3 ft.; scribed T3N R9W S16 BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT.
Set 4" x 4" x 60" white painted Fir post 1.0' N.W. of pipe.

Dated April 26, 1960

Restored by Robert Cop under my direction.
Robert Cop, Forestry Aide

Present and witnessed by G. Nylund



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401