

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

Uncovered a 74 year old line blaze S 89° 23'E at 111.9 ft. and an original at 831.4 ft. Other originals were found in the same vicinity on the same line, as well as more recent blazes.

Uncovered an original line blaze S 0° 09'W 1175.6 ft.

The county corner between Sections 2 and 3 in the opposite direction, N 0° 09'E 1144.1 ft., is found and restored. More recent line blazes of different ages were found on this line, as well as west of the intersection (see below).

RESTORATION by unknown party, notes recorded in County Surveyor's office 1887.

No evidence of restoration found.

RESTORED

Var. 21°

At intersection of original blazed lines and the County corner (see above), set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T6S R9W S2 S3 S10 S11 1962 RS559", 33 inches in ground, and from which a:


- 40" Hemlock bears S32 1/2 E 29.7 ft.; scribed T6S R9W S11 BT RS559.
- 20" Hemlock bears S9W 12.3 ft.; scribed T6S R9W S10 BT.
- 50" Fir stp. bears N16W 56.0 ft.; scribed T6S R9W S3 BT.
- 66" Fir stp. bears N9E 59.7 ft.; scribed T6S R9W S2 BT.

Oregon State Board of Forestry metal location poster on 20" Hemlock BT.

Set 4" x 4" x 72" white painted Cedar post 1.5' NW of corner pipe.

Dated August 7, 1962

Restored by



Present and witnessed by John Hollingsworth
Lance Hazelbaker
Curt Stone

VOID
SEE
LATER
SURVEY
FOR
RESTORATION

SEE FOLLOWING
PAGE # 426