

County Surveyor's Record, Tillamook County Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 10 and 15, T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (found in place shortened to 24" by rot, scribes 1/4 S visible) from which a:

5" Vine maple bears N20W 21 lks.; vine maple clump in place.

4" Vine maple bears S24E 7 lks.; missing.

5 lk. Creek, course North, bears East 9.06 ch.; in place.

RESTORED

Var. 20 1/2° E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S10 S15 1962 RS559", 32 inches in ground, at corner point with above post along E side of pipe, and from which a:

6" Fir bears N87E 22.0 ft.; scribed 1/4 S10 BT.

11" Fir bears S37W 51.0 ft.; scribed 1/4 S15 BT RS559.

Oregon State Forestry Department metal location poster on 6" Fir BT.

Set 4" x 4" x 72" white painted Cedar post 1.5' NW of corner pipe.

Dated August 7, 1962

Restored by John Hollingsworth under my direction.
John Hollingsworth, Engineering Technician



Present and witnessed by Lance Hazelbaker

X 1/4 Cor
S. 3rd
10-6-59

559