

*1/4 Cor S. 18 & 19
18-2 N.S. 8.*

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 18 and 19, T2S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 12" x 10" x 9" (now missing, point falls in slide) from which a:

10" Hemlock bears N68°E 84 lks.; now 20" stump, scribes 1/4 S BT exposed.

18" Cedar bears S73°E 44 lks.; now missing, point falls in slide.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S18 S19 1962 RS401", 28" in ground, in mound of stone, and from which a:

8" Alder bears S27°W 14.6 ft.; bark scribed 1/4 S 19 BT RS401.

108" Fir stump bears N22 1/2°E 66.1 ft.; scribed 1/4 S 18 BT.

Oregon State Forestry Department metal location poster on 5" Alder S89W 9.5 ft.


Set 4" x 4" x 52" white painted Cedar post 2 ft. NE of corner pipe.

Dated October 25, 1962

Restored by *Billy E. Davis* under my direction.
Billy E. Davis, Transitman



Richard A. Morris



Present and witnessed by D. Fletcher