

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner for Section 19 (West side), T2S, R8W,
W.M., Tillamook County, Oregon.

ORIGINAL

*1/4 cor
w. Bdry
19-25*

Stone 12" x 8" x 6" (unmarked stone 14" x 8" x 6" found in place) from
which a:

8" Hemlock bears S57°E 85 lks.; now 37" Hemlock snag 15' high, scribes
1/4 S exposed.

18" Hemlock bears S5°W 50 lks.; now missing.

RESTORED

Var. 21 1/2 E

Chisled "X" on top of, and built stone mound around, original stone
from which a:

24" Hemlock bears N50 1/2 E 44.4 ft.; scribed 1/4 S 19 BT RS401.

8" Cedar bears N13°E 20.0 ft.; scribed 1/4 S19 BT.

Oregon State Forestry Department metal location poster on 8" Cedar BT.
Set 4" x 4" x 52" white painted Cedar post 2.0 ft. Northeast of
corner stone.

Dated October 25, 1962.

Restored by Allan E. Duncan under my direction.
Allan E. Duncan, Forestry Aide



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by D. Fletcher
C. Curl

434