CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T.3N, R.10W, W.M., Tillamook County, Oregon.

ORIGINAL

11-3,N, 10.

Post (now missing) from which a:

28 Alder bears N5W 45 lks.; now missing.

Vinc Maple S16°W 23 lks.; now missing.

Vinc Maple S10°E 32 lks.; now missing.

RESTORATION by W. A. Markham, 1953, Railroad rail put in place by J. H. Markham (found 6" below ground) from which a:

72 Spruce Spar Tree bears N1° 11' W 81.4 ft.; now missing, found spar tree approximately 150 ft. North.

16" Alder bears N75° 41' E 137.3 ft.; in place, no scribes.

N.E. Corner of Barn bears S13º 03' W (no distance given) in place.

**REWITNESSED** 

16 Spruce bears S39W 92.0 ft.; scribed T3N R10W S14 BT RS401. 26 Spruce bears N543/4E. 108.7 ft.; scribed T3N R10W S12 BT. 9 Alder bears S59 1/4E 61.1 ft.; bark scribed T3N R10W S13 BT.

Cool Ck. Bears West 89.0 ft. course South.

Oregon State Forest Department metal location poster on fence post 588°W 16.0 ft.

Dated March 27, 1963.

Restored by

Billy E. Davis

under my direction.

Present and witnessed by H. Russell

A. Duncan

D. Fletcher

REGISTERED OREGON LAND SURVEYOR

Richard A. Mo

401