

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T.3N,
R.10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing Point Falls in cat road) from which a:

- 40" Cedar bears N50°W 28 lks.; now 46" stump, bottom of face remaining, also axe marks on butt log (now bears N13W, see below).
- 36" Hemlock bears S45°E 49 lks.; now 34" stump, bottom of face remaining (now bears S50E, see below).
- 36" Hemlock bears S31°W 70 lks.; now badly decayed stump (now bears S20W, see below).

Note: Survey in 1893 found above BT's with bearings and diameters to be;

- 40" Cedar bears N13°W 28 lks.
- 30" Hemlock bears S50°E 49 lks.
- 28" Hemlock bears S20W 70 lks.

RESTORED

VAR. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R10W S2 S3 S10 S11 1963 RS 401", 32 inches in ground, and from which a:

- 19" Hemlock bears S88E 31.2 ft.; scribed T3N R10W S11 BT.
- 26" Hemlock bears N48E 12.3 ft.; scribed T3N R10W S2 BT.
- 23" Hemlock bears N64W 32.0 ft.; scribed T3N R10W S3 BT RS 401.
- 5" Cedar bears S25W 21.3 ft.; scribed T3N R10W S10 BT.

Oregon State Forestry Department metal location poster on 26" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 1² ft. NE of corner pipe.

Dated March 27, 1963

Restored by Billy E. Davis under my direction.
Billy E. Davis, Transitman

Present and witnessed by A. Duncan
D. Fletcher

