

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14,
T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 12" Fir bears S50°E 39 lks.; now missing.
- 15" Fir bears S78°W 29 lks.; now missing.
- 12" Fir bears N49°W 28 lks.; now 20" uprotted stump, scribes R9W visible.
- 12" Fir bears N23°E 21 lks.; now missing.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T6S R9W S11 S12 S13 S14 1961 RE2311", 32 inches in ground, and from which a:

- 43" Fir bears S28°W 30.4 ft.; scribed T6S R9W S14 BT RE2311.
- 17" Hemlock bears N63°W 41.9 ft.; scribed T6S R9W S11 BT.
- 27" Fir bears N9°E 82.9 ft.; scribed T6S R9W S12 BT.
- 5" Alder bears S65°E 12.4 ft.; scribed T6S R9W S13 BT (in bark).

Oregon State Forestry Department metal location poster on 27" BT.
Center Line of State Highway 18 bears East 84.0 ft.

Set 4 x 4 x 72" white painted Cedar post 2.0 ft. SE of corner pipe.

Dated March 5, 1962

Restored by *Billy E. Davis* under my direction.
Billy E. Davis, Transitman



Present and witnessed by R. Schulson

*SE. Cor
11-6-S.9.*