

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

County corner common to Sections 1 and 2, T6S, R9W, W.M., Yamhill and Tillamook Counties, Oregon.

ORIGINAL

Post (now missing) from which a:

48" Fir bears S88E 14 lks.; now 55" Hemlock snag, scribes T and backcast of BT remaining.

40" Fir bears S34 $\frac{1}{2}$ W 40 lks.; now 66" stump, evidence of overgrown face.

Creek, Course NW, bears South 4.34 chains; in place.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY YAMHILL CO. TILLAMOOK CO. 1961 RE2311", 30 inches in ground, and from which a:

Creek, Course N bears West 30.0 ft.

Oregon State Board of Forestry metal location poster on original 40" Fir stump.

Set 4 x 4 x 72" white painted Cedar post 1.5 ft. S.E. of corner pipe.

Dated May 28, 1962

Restored by *Billy E. Davis* under my direction.

Billy E. Davis, Transitman



Present and witnessed by R. Schulson

*Co. line
w. Bdry
1-6, S. 9.*