

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 5, 6, 7 and 8, T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt Stone 16" x 10" /<sup>x8"</sup>(now missing) from which a:

- 5" Maple bears N58W 31 lks.; missing.
- 5" Hemlock bears N37E 44 lks.; missing.
- 30" Hemlock bears S42E 32 lks.; now 30" stub 8' high, face and scribes rotted away.
- 8" Hemlock bears S34W 27 lks.; missing.

Original line blazes to the North and East.

Ravine bears West 1 chain, now in place using slope distance.

Ridge bears East 7 chains, now in place using slope distance.

Ridge bears South 5.50 chains; now in place using slope distance.

RESTORED

Var. 21 1/2"

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R8W S6 S5 S7 S8 1962 RS401", 12" in ground, in mound of stone 18" high, and from which a:

- 22" Hemlock bears S33W 118.9 ft.; scribed T1S R8W S7 BT RS401.
- 30" Hemlock bears N77W 130.1 ft.; scribed T1S R8W S6 BT.
- Base of rock outcrop bears S33E 47.3 ft.; X B0.

No tree available in NE quadrant.

Oregon State Forestry Department metal location poster on 6" Alder N41W 14.5 ft.

Set 4" x 4" x 52" white painted Cedar post 1.0' NE of corner pipe.

Dated June 27, 1962

Restored by



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401

Present and witnessed by D. Fletcher

SW. Cor  
5-1-S-8