

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 2 and 11, T6S, R9W,
W.M., Tillamook County, Oregon.

ORIGINAL

Post (now only rotted wood remaining in well shaped post hole) from
which a:

- 30" Alder bears N15W 38 lks.; now 24"; rotted out inside, evidence of
old face cast remaining (original size was probably 3").
- 4" Vine Maple bears S20E 28 lks.; Vine Maple clump in place.

Creek, 25 links, course South, bears East 1.26 chains; now in place.
Original line blazes East and West.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY 1/4 S2 S11 1962 RS359", 30 inches in ground,
and from which a:



- 24" Spruce bears S80 1/2 E 50.5 ft.; scribed 1/4 S11 BT RS359.
- 44" Fir stump bears West 35.7 ft.; scribed 1/4 S2 BT.

Oregon State Forestry Department metal location poster on Original
Alder BT.

Set 4 x 4 x 72" white painted Cedar post 1.5 feet SE of corner pipe.

Dated April 13, 1962

Restored by



Present and witnessed by John Hollingsworth

1/4 cct.
S-Block
2-b.S.9.