

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 30 and 31, Township 3 North,  
Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 12" x 6" basalt stone, now in place marked 1/4, from which  
a:

26" Hemlock bears N41W 81 lks; now 40" stub 3' high.  
11" Hemlock bears S36E 17 lks; now 18" stub 2' high,  
exposed scribe marks BT.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S30 S31 1952 2311," 2 1/2"  
in ground. Placed 1/4 stone on north edge of pipe and raised  
mound of stone around corner pipe, from which a:

30" Fir snag bears S56E 25.0°; scribed 1/4 S31 BT RE 2311.  
30" Fir stump bears N15W 70.9°; scribed 1/4 S30 BT.

Placed an Oregon State Board of Forestry metal location poster on  
41" Fir stump and marked it: Sec 31 T3N R7W Sec Cor 37 lks N88E.

Dated April 22, 1952.

This corner was restored by Don D. Davis  
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chairman