

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 5 and 6, Township 2 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

13" x 8" x 7" stone, now missing, from which a:

72" Fir bears S35E 11 lks.; now 75" stump, exposed scribe marks BT.

18" Cedar bears N64W 32 lks.; now missing.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S6 S5 1953 2311," 2½" in ground. Raised mound of stone around corner pipe, from which a:

56" Fir snag bears N05°W 37.6°; scribed 1/4 S6 BT.

75" Fir stump bears S35°E 7.3°; scribed 1/4 S5 BT RE 2311 (below original face).

Placed an Oregon State Board of Forestry metal location poster on original BT, now 75" Fir stump, on side of stump facing logging road, and marked it: Sec 5 T2N R8W 1/4 Cor 10.2 Ft. N20W.

Dated January 8, 1953.

This corner was restored by Don D. Davis,
Don D. Davis Assistant Forest Engineer

under my direction.



Present and witnessed by Robert A. Young, Compassman

Robert J. Schwalen, Chainman.