

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 26 and 27, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found) from which a:

10 lk. Creek bears South 5 chs.; Course S40W, Now 24" in place.

REESTABLISHED

Var. 21 $\frac{1}{2}$ °E

At a point on the true line between Sec. Cors. 22, 23, 26, 27 and 26, 27, 34, 35, and 5 chs. North of above creek, set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S27 S26 1959 RS401", 30 inches in ground, and from which a:

18" Hemlock bears S75 $\frac{1}{2}$ °E 27.3 ft.; scribed 1/4 S26 BT RS401.

19" Hemlock bears N79 3/4°W 13.5 ft.; scribed 1/4 S27 BT.

Oregon State Board of Forestry metal location poster on 19" Hemlock. BT.

Set 4" x 4" x 60" white painted Cedar post 1.2' S.W. of pipe.

Present and witnessed by H. Russell
R. Cop

One Quarter corner common to Sections 23 and 24, T1N, R10W, W.M., Tillamook County, Oregon.

REESTABLISHED

Var. 21 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S23 S24 1959 RS401", 30 inches in ground, between roots of Hemlock, in mound of stone, and from which a:

25" Fir bears N82 $\frac{1}{2}$ °W 26.2 ft.; scribed 1/4 S23 BT RS401.

26" Fir bears S23°W 38.2 ft.; scribed 1/4 S24 BT.

Oregon State Board of Forestry metal location poster on 16" Hemlock N25°W 1.0'

Set 4" x 4" x 60" white painted Cedar post 1.5' SE of pipe.

Corner is 10.0' South of ridge top, course N80°W.

Present and witnessed by H. Russell
R. Cop
E. Mylund
D. Jones

Dated December 31, 1959

Reestablished by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401