

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 11 and 14 (west end),
T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 4" Maple bears S3°E 67 lks.; now missing, clump of Maples in place.
- 72" Spruce bears N2½°E 58 lks.; now 72" stub 10' high, face and scribes burnt away.
- 2 link cr. course NW bears North 640 lks.; now in place (N35W)

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S11 S14 S15 1964 RS401", and from which a:

- 9" Hem. bears S55½°E 24.3 ft.; scribed T2S R9W S14 BT RS401.
- 12" Hem. bears N47½°E 83.2 ft.; scribed T2S R9W S11 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SW of corner pipe.
Oregon State Forestry Department metal location poster on 8" Hem. N89°W 8.8 ft.

Dated February 2, 1965

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan
C. Curl

