

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 24 and 25, T3S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 60" Fir bears S15E 18 lks.; now 54" snag (S8E) face and scribes rotted away.
- 12" Hem. bears N32W 49 lks.; now 31" stub, scribes 4S visible, remainder of face covered.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S24 S25 1965 RS401", 32 inches in ground, and from which a:

- 54" Fir snag (orig.) bears S8E 12.1 ft.; scribed 1/4 S25 BT.
- 38" Hem. bears N9 1/2 E 27.2 ft.; scribed 1/4 S24 BT RS 401.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on 54" Fir snag BT.

Dated June 10, 1965

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Morris
MAY 10 1957
Richard A. Morris
401