

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 29, 30, 31, and 32, Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

18" x 16" x 12" basalt stone, now in place marked with 1 notch on south face and 5 notches on east face, from which a:

- 30" Fir bears N25E 28 lks.; now 42" stub 6" high N28°45'E 18.5' (slope distance), scribe marks BT exposed.
- 16" Hemlock bears S35E 62 lks.; now 20" down stub out of place, exposed part of scribe mark T.
- 18" Hemlock bears S40W 45 lks.; now missing.
- 4" Fir bears N60W 12 lks.; now missing.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W S30 S29 S32 1953 2311," 2 1/2" in ground. Raised mound of stone around corner pipe, from which a:

- 41" Fir snag bears S84°E 59.3'; scribed T3N R8W S32 BT.
- 60" Fir snag bears N53°W 5.0'; scribed T3N R8W S30 BT RE 2311.
- 48" Fir stump bears S53°W 46.6'; scribed T3N R8W S31 BT.
- 48" Fir stub 8" high bears N44°15'E 39.0'; scribed T3N R8W S29 BT.

Placed an Oregon State Board of Forestry metal location poster on 41" Fir snag BT and marked it: Sec 30 T3N R8W Sec Cor 59.3 Ft. N84°W.

Dated January 6, 1953.

This corner was restored by Don D. Davis Assistant Forest Engineer under my direction.



Present and witnessed by Robert A. Young, Compassman.

Robert J. Cowan, Chainman.